

Menu

HISTORY FILE MAP for year 2003


REALTIME

PLAYBACK

RECALLED REALTIME

RECALLED PLAYBACK

155.04:32-04:34: 7m real-time 1024bps data lost due to short turn-around time and subsequent
155.04:34-04:39 late AOS at DSN34. DSN43 could not support due to faulty Antenna Servo
Interface card and pass was transferred to DSN34. DR C102445 refers.



157.21:16-21:27: 11m real-time 1024bps data lost due to lost connection engine at DSN24.
DR G102846 refers.